

March 31, 2025

Attn: Audrey Maldonado Mohawk Valley Land Bank P.O. Box 53 Little Falls, New York 13365

Re: Pre-Demolition Asbestos Survey: 22 Maple Street, Gilbertsville, New York 13376

Dear Ms. Maldonado,

Enclosed are the analytical results, sample location plan, license and certifications and chains of custody for sampling and analysis of suspect building materials associated with the above referenced location.

Scope

On March 25, 2025, New York State Department of Labor certified inspector C. Connelly (DOL Cert #. 24-62XJ3-SHAB) conducted the asbestos inspection and survey with procedures and guidelines in accordance with New York State and EPA protocol.

Analysis Methods

Lozier Environmental Consulting, Inc. is accredited through New York State Department of Health ELAP (Lab ID# 11770) for Solid and Hazardous Waste and Air and Emissions for Bulk Asbestos Fiber Analysis by polarized light microscopy (PLM). The analysis methodology used for asbestos bulk samples is as follows: New York State Department of Health ELAP Method 198.1 and 198.6; *Polarized Light Microscopy Methods for Identifying and Quantitating Asbestos in Bulk Samples*. Asbestos containing materials are defined as those materials containing greater than 1.0% asbestos.

Limitations

This Survey is not subject to interpretation by parties other than the authors of this document. Observations noted and recorded are intended to represent the conditions that existed at the subject site at the time and date that the observations were made. Lozier Environmental Consulting, Inc. accepts no responsibility for the content of building materials within areas or spaces that were unknown to us or not reasonably accessible.

Summary of Asbestos Containing Materials

LOCATION	MATERIAL	COND.	CLASS	QUANTITY
Exterior Windows	Grey Window Glaze	Poor	NOB	12 Square Feet (7 Windows)

Notes:


- Condition: Good = No visible damage and/or very limited deterioration. Fair = visible damage or deterioration on less than 25% of the material. Poor = visible damage or deterioration greater than 25%.
- All quantities are approximations and should be verified by contractor prior to removal.


Lozier Environmental Consulting, Inc. appreciates this opportunity to provide you with our professional services. If you have any questions, please contact me at 585-654-9080.

Sincerely,


Ben Frank Project Manager

SAMPLING LOCATION PLA





Project: 22 Maple St Date: 3/25/2025, 11:21am Creator: Chris Connelly



Project: 22 Maple St Date: 3/25/2025, 11:22am Creator: Chris Connelly



Project: 22 Maple St Date: 3/25/2025, 11:22am Creator: Chris Connelly



2011 East Main Street, Rochester, New York 14609 Phone: (585) 654-9080 Fax: (585) 654-9662 www.LozierEnv.com ELAP #11770

Mohawk Valley Land Bank Client:

P.O. Box 53

Little Falls, New York 13365

Project Site: 22 Maple Street, Gilbertsville, New York 13376

Attn:

Audrey Maldonado

Laboratory No.: 79070 Date Received: 3/26/25

Report Date: 3/27/25 Analysis Date: 3/27/25

Page: 1 of 1

Chain of Custody in Following Pages

SAMPLE INFORMATION

Analyst: J.Savoie Sample Date: 3/25/25 Location: Exterior 2 Type of Sample: Bulk Asbestos Number of Samples: Sampler: C. Connelly

ASBESTOS BULK LABORATORY REPORT

Client ID	Lab ID	Sampling Location	Description	PLM Asbestos Fibers (%)	PLM Total Asbestos (%)	2 0 E	C L A s s	PLM Non-Asbestos Fibers (%)	Matrix Material (%)	TEM Results Asbestos (%)
1	79070-1	Exterior Windows	Grey Window Glaze	Chrysotile 4.3%	4.3%		NOB	None Detected 0%	95.7%	N/A
2	79070-2	Exterior Windows	Grey Window Glaze	Chrysotile 3.8%	3.8%		NOB	None Detected 0%	96.2%	N/A
	`									

Analysis Method: Polarized Light Microscopy (PLM) - Friable Material: EPA 600/M4-82-020(F1), New York State ELAP Item 198.1(F) and New York State ELAP Item 198.6(NOB)

Analytical results relate only to the sample received and analyzed. This report shall not be reproduced except in full without the written approval of the laboratory.

Material Classification: F = Friable, NF = Non-Friable, F1=EPA 600/M4-82-020, NOB = Non-Friable Organically Bound.

NAD: No Asbestos detected by TEM analysis N/A: Not applicable; TEM analysis not required

Technical Director



2011 East Main Street, Rochester, New York, 14609

Phone (585) 654-9080 Fax (585) 654-9662 LozierEnv.com

ELAP Accredited No. 11770

PLM/TEM ASBESTOS BULK MATERIAL SAMPLES

Page __1__ of __

Client: Address: P.O. Box 53 Phone # Contact: RECEIVED BY: TRANSPORTED TO: LOZIER ENVIRONMENTAL CONSULTING, INC. Client ID N Audrey Maldonado Little Falls, NY 13365 Mohawk Valley Land Bank Lab ID Email: pm@gmvlb.org Room/Area Location Exterior windows Exterior windows Sample Date: Sampled By: Gilbertsville, NY 13376 No. Samples: 22 Maple St. Color/Description Relinquished By: grey grey 3/25/2025 Lab No.: 790 70 Chris Connelly DATE window glaze window glaze Material Type 2 Contact Client / LM TAT (TEM): Imm. AMA / EMSL TAT(PLM): Imm. 24H (8H) 3 Day 5 Day TEM: Yes No Stop Positive 16:00 24H 48H 3 Day 5 Day TEM's Sent On: Layer No. F - ZF NOB + TES



2011 East Main Street, Rochester, New York 14609 Phone: (585) 654-9080 Fax: (585) 654-9662 www.LozierEnv.com

WE ARE YOUR DOL

NEW YORK Departme

DIVISION OF SAFETY & HEALTH LICENSE AND CERTIFICATE UNIT, STATE OFFICE CAMPUS, BLDG. 12, ALBANY, NY 12226

ASBESTOS HANDLING LICENSE

Lozier Environmental Consulting, Inc. 2011 East Main Street, Rochester, NY, 14609

License Number: 29997
License Class: RESTRICTED
Date of Issue: 08/19/2024
Expiration Date: 08/31/2025
Duly Authorized Representative: Amy Pusateri

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.

Amy Phillips, Director For the Commissioner of Labor

SH 432 (17/71)

Lozier Environmental NYS DOL Asbestos License



2011 East Main Street, Rochester, New York 14609 Phone: (585) 654-9080 Fax: (585) 654-9662 www.LozierEnv.com

NEW YORK STATE DEPARTMENT OF HEALTH WADSWORTH CENTER



Expires 12:01 AM April 01, 2025 Issued April 01, 2024 Revised April 02, 2024

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. VICTORIA R. KAPTEIN LOZIER ENVIRONMENTAL CONSULTING, INC 2011 EAST MAIN STREET ROCHESTER, NY 14609 NY Lab Id No: 11770

is hereby APPROVED as an Environmental Laboratory for the category ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE All approved subcategories and/or analytes are listed below:

Miscellaneous

Asbestos in Friable Material

Item 198.1 of Manual

EPA 600/M4/82/020

Asbestos in Non-Friable Material-PLM Item 198.6 of Manual (NOB by PLM)

Department of Health


Serial No.: 69235

Property of the New York State Department of Health. Certificates are valid only at the address shown and must be conspicuously posted by the laboratory. Continued accreditation depends on the laboratory's successful ongoing participation in the Program. Consumers may verify a laboratory's accreditation status online at https://apps.health.ny.gov/pubdoh/applinks/wc/elappublicweb/, by phone (518) 485-5570 or by email to elap@health.ny.gov/pubdoh/applinks/wc/elappublicweb/.

Page 1 of 1



STATE OF NEW YORK DEPARTMENT OF LABOR ASBESTOS CERTIFICATE



The following letters denote the corresponding license classification found on the technician's license:

A - Handler

B - Allied Trades

C - Air Sampling Technician

D - Inspector

E - Management Planner

F - Operations & Maintenance

G - Supervisor

H - Project Monitor

I - Project Designer

Christopher Connelly